



FIG 1 WRECKAGE OF ZK-NZP LOOKING NORTH OVER LEWIS BAY




FIG 2 LOOKING SOUTHWEST PAST BURNT OUT CABIN TOWARDS MT EREBUS




FIG 3 LOOKING WEST ACROSS WRECKAGE OF ZK-NZP TOWARDS NORTH-WEST SHORE OF LEWIS BAY




FIG 4 AFTERMATH OF INTENSE FIRE IN CABIN AREA




FIG 5 TOP OF RIGHT WING AND RIGHT CABIN SIDE OVER WING DOOR AREA